

# **ST MARY'S VICARAGE RELOCATION**

## **PHOGRAPHIC RECORD**

**As Is - June 2020**

**EXTERIOR**



North East view



North view



North West view



North West view



South West view



South view



South view



East view



Front Entry view



Chimney detail




view of Vicarage from drone




view of Vicarage and grounds


**INTERIOR**  
**ENTRY**






LOUNGE




DINING / FAMILY



HALLWAY




KITCHEN & PANTY









STUDY





TOY ROOM




SCULLERY & LAUNDRY





STAIRWAY




STAIRWAY




**BEDROOM 1**



BEDROOM 2




**BEDROOM 3**







**BEDROOM 4**




**BEDROOM 5**




**BEDROOM 6**



SUN PORCH




**BATHROOM**



1 VICARAGE - EXISTING FLOOR PLAN SHOWING DEMO - UPPER FLOOR  
A-200 1:32 @ A1



DINING / FAMILY CHIMNEY REMOVAL



1 VICARAGE - EXISTING FLOOR PLAN SHOWING DEMO - GROUND  
A.200 1:50 @ A1



Dining / Family fireplace (prior removal)




Dining / Family fireplace (after removal)



Fireplace (after removal)

**LOUNGE – STUDY/ UPSTAIRS BEDROOM 4 CHIMNEY REMOVAL**



Upstairs Bedroom 4 fireplace (prior removal)



Upstairs Bedroom 4 fireplace (after removal)



Lounge fireplace (prior removal)



Lounge fireplace (after removal)



Fireplace (after removal) - viewed from Study